

Square Recess Bits

1/4" Hex Insert Bits

Part Number	Point Size	Nominal Size In.	Overall Length In.	mm
950-0X•	0	1/16	1	25
950-1X•	1	3/32	1	25
950-2X•	2	1/8	1	25
950-3X•	3	9/64	1	25

1/4" Hex Power Drive

Part Number	Point Size	Nominal Size In.	Overall Length In.	mm
954-0X•	0	1/16	1 15/16	49
954-A-0X	0	1/16	2 3/4	70
954-C-0X	0	1/16	6	152
954-1X•	1	3/32	1 15/16	49
954-A-1X•	1	3/32	2 3/4	70
954-B-1X•	1	3/32	3 1/2	89
954-C-1X	1	3/32	6	152
954-2X•	2	1/8	1 15/16	49
954-A-2X•	2	1/8	2 3/4	70
954-B-2X•	2	1/8	3 1/2	89
954-C-2X•	2	1/8	6	152
954-3X•	3	9/64	1 15/16	49
954-A-3X•	3	9/64	2 3/4	70
954-B-3X•	3	9/64	3 1/2	89
954-C-3X•	3	9/64	6	152

1/4" Hex Power Drive – Turned Body

Part Number	Point Size	Nominal Size In.	Overall Length In.	mm	Turned Length In.	mm
1950-0X	0	1/16	1 15/16	49	1 1/4	32
1951-0X	0	1/16	2 3/4	70	2	51
1950-1X•	1	3/32	1 15/16	49	1 1/4	32
1951-1X•	1	3/32	2 3/4	70	2	51
1953-1X•	1	3/32	3 1/2	89	2 3/4	70
1950-2X•	2	1/8	1 15/16	49	1 1/4	32
1951-2X•	2	1/8	2 3/4	70	2	51
1953-2X•	2	1/8	3 1/2	89	2 3/4	70
1956-2X	2	1/8	6	152	5 1/8	130
1950-3X	3	9/64	1 15/16	49	1 1/4	32
1951-3X	3	9/64	2 3/4	70	2	51
1953-3X•	3	9/64	3 1/2	89	2 3/4	70

Screw Size	3 & 4	5, 6, 7	8, 9, 10	12-14 1/4
Square Point Size	0	1	2	3

For Quad-rex bits refer to page 14.

Male Square Inserts for Pipe Plugs

1/4" to 1/2" Male Square

Part Number	Male Hex In.	Male Square In.	Overall Length In.	mm
P-1408•	7/16	1/4	1 1/4	32
P-1409•	7/16	9/32	1 1/4	32
P-1410•	7/16	5/16	1 1/4	32
P-1412•	7/16	3/8	1 1/4	32
P-1414	7/16	7/16	1 1/4	32
P-1416•	7/16	1/2	1 1/4	32
P-2010	5/8	5/16	1 1/2	38
P-2012	5/8	3/8	1 1/2	38
P-2014	5/8	7/16	1 1/2	38
P-2016	5/8	1/2	1 1/2	38

Note: For pipe plug inserts use SC and RP bit holders found on page 26.

Double Square Recess Bits

1/4" Hex Power Drive

Part Number	Point Size	Overall Length In.	mm
954-2-DX	2	1 15/16	49

1/4" Hex Power Drive – Turned Body

Part Number	Point Size	Overall Length In.	mm	Turned Length In.	mm
1953-2-D	2	3 1/2	89	2 3/4	70